

# SUNY CANTON CAMPUS SAFETY WALK AROUND 11/8/18

## NEW PROJECTS

(Update #8 as of 2/21/19)

	LOCATION	ISSUES/CONCERNS	ACTION
18-11-B	CARC southwest of parking lot 25	Bollard light is out	Work Order # 82580 submitted 11/9/2018 Physical Plant is ordering new LED fixture 11/29/2018
18-11-D	Heritage, Rushton, Mohawk, Smith emergency exit exterior lights	Lights are out or too dim	Work Order # 82583 submitted 11/9/2018 Old fixtures, if unrepairable may need to upgrade to LED fixtures 11/29/2018
18-11-H	Miller Drive and Nevaldine South	No crosswalk between parking lot 1 and parking lot 9	Crosswalk is not required, issue will be taken care of in future Parking Lot 1 project. 1/30/2018

Updated 2/21/19